

From: [<Wallingford, Jonni B. <wallingfordjb@cdmsmith.com>>](mailto:wallingfordjb@cdmsmith.com)  
To: [<Sheldrake, Sean <sheldrake.sean@epa.gov>>](mailto:sheldrake.sean@epa.gov)  
[<Zhen, Davis <Zhen.Davis@epa.gov>>](mailto:Zhen.Davis@epa.gov)  
CC: [<Vickstrom, Kyle E. <vickstromke@cdmsmith.com>>](mailto:vickstromke@cdmsmith.com)  
[<Scott Coffey <coffeyse@cdmsmith.com>>](mailto:coffeyse@cdmsmith.com)  
[<younghs@cdmsmith.com>](mailto:younghs@cdmsmith.com)  
Date: 8/22/2018 2:04:46 PM  
Subject: Surface Water Sampling  
Attachments: [IMG\\_20180822\\_135208831.jpg](#)  
[Img\\_180822140054749-1.jpg](#)  
[IMG\\_20180822\\_135921135\\_HDR.jpg](#)  
[IMG\\_20180822\\_135929146\\_HDR.jpg](#)  
[IMG\\_20180822\\_135941502.jpg](#)

---

Good afternoon,

The Tieton is currently stationed at Target site 3W (RM 4), sampling for the last 2 hours. The Gravity PR2900 filters are continuously changed as the gauge approaches 15psi (photo 1 and 2).

The Tieton has approximately 30 minutes of sampling left at station 3E, and will relocate to 3NAV to sample next.

Jonni

Photo 1: gauge after filter is changed

Photo 2: filter change using decontaminated tweezers

Photo 3: location 3E facing NE

Photo 4: location 3E facing NW

Photo 5: sampling tube

Get Outlook for Android<<https://aka.ms/ghei36>>